



**Directions to set up 34.92- degree throws sector:**

**1. From the center of the circle, measure one of the outer boundary lines at distance A and make a mark ( # 1 ).**



**2. From Mark #1, measure .6 of length A in the direction of the other outer boundary line and make another mark ( # 2 ).**



**3. From the center of the circle, measure distance A towards Mark #2 to form the second outer boundary line. The result is a 34.92-degree sector.**

